



GEM Technical Data Book Technical Data Book Update, July, 2002 Updating Instructions

Replace the Table of Contents dated 3-01 with the revised Table of Contents dated July, 2002.
Use the new Table of Contents as a guide when inserting the referenced new and revised technical data sheets.

REMOVE	INSERT	NOTES
TD116 (9-99)	TFP1330 (June, 2002) Insert in place of removed sheet.	The 4 and 6 Inch Model DV-1 Deluge Valves are a redesignation for the Model F470.
TD116H (9-99)		The Model F470H Deluge Valves are no longer offered for sale.
TD117W (3-83)	TFP1380 (June, 2002) Insert in place of removed sheet.	The Model DP-1 Dry Pilot Actuator is a redesignation for the Model B-1.
TD119 (12-94)	TFP2180 (June, 2002) Insert in place of removed sheet.	The data sheet for Solenoid Valves For Releasing Service has been reformatted.
TD121 (5-83)	TFP1382 (June, 2002) Insert in place of removed sheet.	The Model MC-1 Manual Control Station is a redesignation for the Model F180. The Model F184 Manual Control Station is no longer offered for sale.
TD127 (2-00)		The Model F114 Supervisory Air Maintenance Device is no longer offered for sale.
TD129 (2-00)		The Model F116 Supervisory Nitrogen Maintenance Device is no longer offered for sale.
TD225 (6-85)		The 1.5 psi, Low Pressure Alarm Switch is no longer offered for sale.
TD340 (6-95)		The EDC-IV Detector Check Valve is no longer offered for sale.
TD350 (4-84)		The Milwaukee Butterball Valves will remain available through the Gem Sprinkler Price Book.
TD578Q (3-01) TD579Q (3-01)		The Model F690 and F692 Concealed Sprinklers are no longer offered for sale.

REMOVE	INSERT	NOTES
TD583 (3-01) TD584 (3-01) TD584M (3-01) TD585A (3-01) TD587F (3-01) TD587H (3-01) TD587M (3-01) TD591 (3-01)	TFP400 (August, 2002) TFP410 (July, 2002) TFP420 (August, 2002 Rev. A) TFP440 (July, 2002) TFP490 (June, 2002) Insert in place of the removed sheets.	The Series LFII Residential Sprinklers are a new product being offered for sale in place of the Model F680, F983, F978, TFP-1, F685, F984, F687 and F993 Residential Sprinklers.
TD595J (3-01)	TFP332 (June, 2002) Insert in place of the removed sheet.	The 16.8 K-factor, Model F892 Sprinklers have been redesignated as the Tyco Fire Products Model K17-231 Sprinklers.
TD595M (3-01)	TFP330 (June, 2002) Insert in place of the removed sheet.	The 16.8 K-factor, Model F892X Sprinklers have been redesignated as the Tyco Fire Products Ultra K17 Sprinklers.
TD596A (3-01)	TFP220 (June, 2002) Insert in place of the removed sheet.	The Model F895 ECOH Sprinklers have been redesignated as the EC-11 & EC-14 Extended Coverage Sprinklers. These sprinklers that had previously been for use in ordinary hazard locations are now also listed for use in light hazard occupancies. In addition a specific application listing for installation of the upright sprinklers under concrete tee construction has been added.
	TFP316 (June, 2002) Insert after TD598M.	Model ESFR-17, 16.8 K-factor, Upright Early Suppression Fast Response Sprinklers are a new product being offered for sale.
TD620B (11-92)		The Type D3 Large Capacity Protectospray Nozzles are no longer offered for sale.
TD703A (3-68) TD703B (3-68)		The Type D4a Protectospray Nozzles are no longer offered for sale.
TD805 (5-89)		Non-recessed Sprinkler Escutcheons will remain available through the Gem Sprinkler Price Book.
TD820 (11-97)		Sprinkler Wrenches are described within the individual sprinkler data sheets.
TD825 (9-84)		Automatic Sprinkler Reserve Supply Cabinets will remain available through the Gem Sprinkler Price Book.